

Optimize Motor Performance with Nexans DriveRx[®] VFD Cable

Problem #1:

High voltage spikes damage cable and cause system failure.

Problem #3:

High frequency noise interferes with data and control signals.

Problem #2:

Bearing currents cause motor failure.

#1: 1 kV Rated XLPE insulated conductors

#2: Three symmetrically placed grounding conductors

#2 & #3: Continuous aluminum sheath

PVC jacket & suitable for use in hazardous locations



www.nexans.ca

Nexans
BRINGS ENERGY TO LIFE